







Replacement Impellers

Avail. In Plastic (i) and Bronze (B)	LMI Part #	Outside Diameter	Overall Height	Thickness	Inlet Diameter	Motor HP rotation	OEM Pump Model Part #
	LM-1i	2-3/4	1-3/8	7/16	1-1/2	1/12 CCW	S-25 / Series 100 812961-111 812961-041 189132, 118431
	LM-1B						
	LM-2i LM-2B	3-3/8	1-1/2	5/8	1-1/2	1/6 CCW	H-32 / S-35 Only 816322-111 816322-041 HV / 2" 189128 189128LF
	LM-2iBG (B)						
	LM-3i	3-7/8	2-1/2	1	2	1/4 CW	S-45 / 2-1/2S / 3LD 816305-328 816305-058 118876 118440
	LM-3B						
	LM-4i	4-1/4	2-3/8	7/16	1-9/16	1/6 CCW	H-41 / 1PR 816301-325 816301-055 118830 118612
	LM-4B						
	LM-5i	4-1/4	2-1/2	1	2	1/3 CCW	S-46 / 3HD 816305-325 816305-055 118675 118439
	LM-5B						
	LM-6i	4-3/4	2-3/8	7/8	2	1/2 CW	S-55 / PD-35 816304-321 816304-051 118630 118627
	LM-6B						
	LM-7i	5	2-3/8	7/16	1-9/16	1/4 CW	H-51 / 60-11 816302-319 816302-049 186441 186360
	LM-7B						
	LM-8i	5-1/4	2-3/8	7/16	1-9/16	1/3 CW	H-52 / 60-2 816302-317 816302-047 186441 186359
	LM-8B						
	LM-9i	5-1/4	2-1/2	5/8	1-9/16	1/2 CW	H-53 / 60-13 816303-317 816303-047 P61010 186368
	LM-9B						
	LM-10i	5-1/4	2-3/8	7/8	2	3/4 CW	S-57 / H-54 / PD37 / 60-14 816304-317 816304-047 118626 118629
	LM-10B						

Len Myers & Associates, Inc.

PO Box 805, Wickliffe, OH 44092

Ph. (614)861-6065 / Fx. (614)861-6590 / info@len-myers.com